

Start here.

a)

* correct PPE should be worn

* For the process of manufacturing this bracket it has the risk of using power tools, hand tools and machines. For when using tools and machinery it has a high noise level and is dangerous to the ears and slowly leads to deafness if ear protection ~~is~~ is not worn.

Eyes being exposed to tools and machinery is a risk and can lead to blindness if eye protection is not worn.

Sharp edges of the bracket after being made can be a risk and gloves or hand protection should be used.

Hands being caught in machinery is a risk and should learn about the machine before using or get shown how it works.

~~we~~ make sure when making the bracket that you are comfortable and confident with using the tools because it is a risk to you and other workers if you aren't comfortable with using that tool.