Start here.		
@ Risk assessment		
Risle	Risk Level	Actions to reduce risks
Sharp and of scribe	Low	Use appropriately PAE
Sharp edges of quillotine	On High	ensure I know how to use it. PPE
Circular Metal Trop saw	High	11 11 11
Crushing risk (hammer)	Melow	Take care wear gloss, PPE
(utting risk (drill press)	Medium	ensure I am advanted to use machine, APE
Eye risk (flying debris)	Modrin	PPE
Cutting risk (swarf)	Low	PPE
Trip hazard (tools de)	Low	Ensure working area is clear.
Falling tools	Low	Ensure working area is clear.  PPE, ensure tools are in middle of borch.
	1	1