

I would calm the customer John
then the act him to show me the
aren which lost power. I would then
get him to show me where the meter box
is and See if the suitch for that
Section was off.
If the smitch was off, I would then
it back on and see if it turned the
power on. If it did the dob is done.
If the when I transd the suitch
back on F and the porer was still out
I would check to see if a sase had
boken and test the cables to see If
that is the problem.
Wear personal protection equipment and isolate
the sight to test the cables because
they may be damaged.