

One section of the costoners business premises has lost power and is affecting production.

firstly talk to the customer and see what is the problem be polite that he has, talk to him in a propper tone as he is wate. Ask him questions like when did this happen, what time, where are you located, what the extent of the power loss, after you have taken details assess he time you can arrive and notify him, being there as soon as possible is best as his company is Coosing money one Line. Once there talk to the person / carolomer that of called you (no one else) and ash them to show for the extent of the dernage, when it brappeness, when there any Hornes, where the madeswitch board is the building. Once you have located the smitch board, tell the person / customer to save any data on Computers, machines or anything what to sended them in that how. Check their this has been done and notify the costoner that you are



now having a look at reasons for the loss of supply and its a procaution that it anything his the brappens, e.g. loss of power to the other section. When checking In switch board check the Main Scrifel Boards Switch and see if it hasn't been tripped or in the off possistion, chuch with Secondly, more to the other RCD's that protect equipments the board (and people) that they wither havn't been totaled tripped and are working fine, (Shald be testeed every month.) Next, check the fires that protect the overlow of power, and chel for faily the fises or danaged lives, by an known Lee that works are isolate gown, then change hise and horn pour on and see if the has worked If nothing is among the than the problem may be the man power cables that on the pour to the servior, test these hours and check for faith, dernege wars



and old cable. After making these chuchs
if there is no way of finding way the
supply is damaged or non-existant notify
the contoner, varbaly and let them know
the churches for van three one whose
8teps you are gaing to take.
for example; pose calling someone with non knowledge
to the site, your boss should be notified also.
· · · · · · · · · · · · · · · · · · ·
<u> </u>
Thecking the fises and 2000' is that if they one
faulty or tripped, this is the manner reusen
that the power may go out due to it borne
Shutting off power for protection of the equipment.