

Question 23 (3 marks)

Describe the process you should use to measure a resistor with a nominal value of $1\text{K}\Omega$, using an analogue ohmmeter.

3

Make sure the ~~meter~~ meter reads absolute zero before connecting and is on the correct setting, connect to resistor in ~~series~~ parallel.