



- 1) IF the ~~busine~~ customer has 'backup power supply' then switch over to it.
- 2) Find Distribution board (DB).
- 3) open DB and Find Fault.
- 4) if no fault in DB then ~~find~~ find the Sections circuit breaker board or fuse board and find fault
- 5) once fault found, isolate, lockout, ~~and~~ proceed w/ test and proceed to fix fault.
- 6) once fixed unlock, un-isolate and test to see if you are successful.

PPE

- gloves
- glasses